## APPENDIX VI AGENCY ADDRESSES

For the convenience of applicants, below is a listing of mailing addresses for the federal and state agencies and a summary of key documentation that applicants are required to submit according to the PWTF General Permit.

**I. Email addresses** for state contacts to confirm annual 7Q10 low flow for a facility and other questions on the PWTF General Permit:

Massachusetts:

Robert Kubit (robert.kubit@state.ma.us)

New Hampshire:

Dennis Greene (Dennis.Greene@des.nh.gov)

## II. Mailing Address for U.S. Environmental Protection Agency

A. **Notice of Intent (NOI)** for facilities located in Massachusetts and New Hampshire (See Appendix IV).

The completed, signed NOI formats and attachments must be submitted to EPA electronically at: pwtf.generalpermit@epa.gov or mailed to:

US EPA, Region 1 Office of Ecosystem Protection PWTF GP Coordinator (OEP06-1) 5 Post Office Square, Suite 100 Boston, MA 02109-3912

B. **Notice of Termination (NOT)** for facilities located in Massachusetts and New Hampshire (See Appendix V).

E-mailed to: pwtf.generalpermit@epa.gov or mailed to:

U.S. EPA, Region 1 Office of Ecosystem Protection PWTF GP Coordinator (OEP06-1) 5 Post Office Square, Suite 100 Boston, MA 02109-3912 C. **Discharge Monitoring Reports (DMRs)** and other required reporting — **Only if** a permittee has submitted an opt-out request from electronic reporting using NetDMR and has received authorization from EPA to do so, the permittee should mail hard copy DMRs and other reports to:

US EPA, Region 1 Office of Environmental Stewardship (OES) Water Technical Unit (OES4-SMR) 5 Post Office Square – Suite 100 Boston, MA 02109-3912

## III. Mailing Addresses for Massachusetts Department of Environmental Protection (MassDEP)

- A. Only Massachusetts facilities that are seeking coverage under the PWTF General Permit for the first time <u>and</u> discharge to Outstanding Resource Waters (ORW) or High Quality Waters must:
  - Submit a completed, signed copy of EPA's suggested NOI form (or another format of official correspondence containing all of the information required in the NOI instructions found at Appendix IV) to:

Massachusetts Department of Environmental Protection Division of Watershed Management 8 New Bond Street Worcester, MA 01606

B. All facilities located in Massachusetts must submit signed copies of all **Discharge Monitoring Reports** (DMRs) and other required reports (excluding toxicity reports) to:

MA Department of Environmental Protection Bureau of Water Resources, NPDES 1 Winter St, 5th Floor Boston MA 02108

**And** to the appropriate MassDEP region below:

MA Department of Environmental Protection Western Regional Office 436 Dwight Street Springfield, MA 01103 Main telephone: 413-784-1100 MA Department of Environmental Protection Southeast Region Main Office 20 Riverside Drive Lakeville, MA 02347 Main telephone: 508-946-2700

MA Department of Environmental Protection Northeast Region 205B Lowell Street Wilmington, Massachusetts 01887

Main Phone: 978-694-3200

MA Department of Environmental Protection Central Region 8 New Bond Street Worcester, Massachusetts 01606 Main Phone: 508-792-7650

C. All facilities located in Massachusetts must submit copies of **toxicity tests** (when required) to:

MassDEP Surface Water Discharge Permit Program 8 New Bond Street Worcester, Massachusetts 01606

## IV. Mailing Addresses for New Hampshire Department of Environmental Services (NHDES)

New Hampshire facilities must submit a copy of the <u>Notice of Intent</u>, <u>Notice of Termination</u>, and all other reports required under the PWTF general permit to:

New Hampshire Department of Environmental Services Water Division, Wastewater Engineering Bureau 29 Hazen Drive, P.O. Box 95 Concord, NH 03302-0095

If a New Hampshire facility is submitting monthly DMRs through NetDMR, hard copies of the DMRs do *not* need to be sent to the state.