Municipality/Organization:	Town of Dighton, Ma
EPA NPDES Permit Number:	MAR041105
MassDEP Transmittal Number	: W-040738
Annual Report Number	Year 10
& Reporting Period:	April 1, 2012 – March 31, 2013

# NPDES PII Small MS4 General Permit Annual Report (Due: May 1, 2013)

#### **Part I. General Information**

Contact Person: Thomas J. Pires	Title:	Board of Selectmen/ Board of Health
Telephone #: (508) 669-6431		Email: debpi54@comcast.net
Mailing Address: 979 Somerset Ave Dighton, Ma 027	15	

#### Certification:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature:	
Printed Name:	Thomas J. Pires
Title:	Chairman Board of Health
Date:	5/2/2013

Part II. Self-Assessment

## Part III. Summary of Minimum Control Measures

### 1. Public Education and Outreach

BMP ID #	BMP Description Continue working with schools to get info out to public	Responsible Dept./Person Name Thomas J. Pires	Measurable Goal(s) Expansion of Program	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any) Storm Water is still part of the curriculum in local schools. Bristol County Agricultural High School continues field work for outfall monitoring as part of their program. They also planted a rain garden.	Planned Activities         Students from Bristol County         Agricultural High school will         continue to identify and map         coordinates of outfalls and will do         sampling in the future.
1-2 Revised	Provide storm water info in public area at Town Hall	Thomas J. Pires	Continue to have information on Stormwater available in Town Hall for the Public	Ongoing	Ongoing
Revised					
Revised		· · · · · · · · · · · · · · · · · · ·	 		
Revised					
Revised					

1-3	Work on methods of getting info out to the public re: storm water	Thomas J. Pires	Continue to explore new sources to educate public on importance of Storm water monitoring and control	Information remains available in public buildings within the town, Storm water addressed on local cable television and during Selectmen's Meeting	Continue to pursue new way of getting information out to public

## 2. Public Involvement and Participation

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
2-1	Research infiltration basins for stormwater disposal and management	Board of Health Planning Board	To conduct site visits semi- annually of existing above or below ground systems to ensure they are being maintained and functioning properly	The type of system to be installed for Storm water control still rest with the Planning Board and Consulting Engineer.	Board of Health and Planning Board will continue to monitor systems. Will modify as situation or regulation change.
Revised					

## 3. Illicit Discharge Detection and Elimination

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
3-1 Revised	Review existing outfall maps and update as needed	Highway Supt.		We continue to monitor basins annually.	Bristol County Agriculture school students are testing for Phosphates and Nitrates See addendum for more info
3-2 Revised	Detect and eliminate discharges	Highway Supt.	Check for any new discharge sites	No new discharge sites located by Storm Drain System Cleaning contractor or by Highway Dept. Employees	Continue to monitor
3-3 Revised	Conduct illicit Discharge Education program	Highway Supt.	Review illicit discharge training with new employees	Covered as part of on the job training for new hires	Task Completed
3-4 Revised	Check on By- Law implementation	Thomas J. Pires	Monitor size of disturbed area that requires permit.	Size of area disturbed that requires a permit remains at 35,000 sq.ft	Continue to monitor and adjust if necessary
3-5	Check on implementation of storm water regulation	Thomas J. Pires	Investigated and resolved one complaint of storm water violations. Found not to be a violation.	Continue to investigate all complaints of potential violations and enforce by law if necessary	Frequency of violations has been reduced due to the awareness of Storm water.
Revised					
Revised					

### 4. Construction Site Stormwater Runoff Control

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
4-1	Revise Site Plan, Review section of Zoning Bylaw	Planning Board	Explore and implement Storm Water Control	No Revisions required	Task Completed
Revised					
4-2	Review procedures for receipt and consideration of information submitted by the public	Board of Health Planning Board Conservation Commission	Propose changes in By- Law regulation resulting from ongoing monitoring or input from residents	Change in land disturbance are approved by Boards and Voters	Task Completed
Revised					
4-3	Revise Site Inspection and Enforcement Control Measures program	Board of Health Planning Board Conservation Commission	Investigation and site visit for all potential violations	Investigated and resolved one complaint	We continue to monitor all construct and land disturbance areas covered by the By – law
Revised					
Revised					
Revised					
Revised					

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
5-1	Review to see if need to modify Zoning By-law	Planning Board	Continue to monitor Storm water by-law conflicts with Zoning By-law or if Storm Water by- law caused any permitting difficulties.	No conflicts found that resulted in permitting difficulties during this reporting period	On going
Revised					
5-2	Revise Subdivision Rules and Regulations	Planning Board	Review Subdivision Rules and Regulations to determine if revision is needed	Review complete for reporting period and no revision needed. No problems encountered or conflicts with existing subdivision rules and regulations and	Ongoing
Revised				storm water by- law and regulations	
5-3.1 Revised	Ensure adequate Long term O&M of BMP'S	Highway Supt Thomas J. Pires	Annual Review process used to determine if O&m of BMP;s are practical in application or if there need to be changes in conditions or processes during reporting period	Completed Review. No major problems detected.	Ongoing
5-3.2	Ensure Adequate Long- term O&M BMP'S	Planning Board	Any proposed change or revisions in 5-3.1 above will be discussed with the Planning Board and any other appropriate Board or Commission	No action required during reporting period	Task Completed
Revised					

## 5. Post-Construction Stormwater Management in New Development and Redevelopment

Revised	 		
Revised			

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
6-1 Revised	Educated Municipal Employees	Highway Superintendent	Update Employee training	Town has updated training program on stormwater management including methods for spotting problems, illicit discharges or suspicious storm drain discharges.	Ongoing
6-2 Revised	Develop & Implement plan to prevent and reduce pollutant runoff from municipal operations	Highway Superintendent	Continue work on Municipal Operations stormwater Plan (MOSP) needed	Town continues to work toward development of MOSP. The Town continues to review and expand MOSP	Ongoing
6-3 Revised	Catch Basin Cleaning	Highway Superintendent	Clean and inspect all catch basins annually	Town purchased a catch basin cleaning truck and will continue to conduct catch basin cleaning annually	Annual Catch basin cleaning will continue
6-4 Revised	Street Sweeping	Highway Superintendent	Continue to perform on all Town Roads bi- annually	Street Sweeping was conducted on some of the Streets due to the late spring we will continue to sweep all Town roads	Street Sweeping of all Town Roads will continue bi-annually
Revised					
Revised					

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 10 (Reliance on non-municipal partners indicated, if any)	Planned Activities
Revised					

## 7. BMPs for Meeting Total Maximum Daily Load (TMDL) Waste Load Allocations (WLA) <<i f applicable>>

### 7a. Additions

#### 7b. WLA Assessment

### Part V. Program Outputs & Accomplishments (OPTIONAL)

(Since beginning of permit coverage unless specified otherwise by a \*\*, which indicates response is for period covering April 1, 2012 through March 31, 2013)

### Programmatic

	(Preferred Unit	ts) Response
Stormwater management position created/staffed	(y/n)	У
Annual program budget/expenditures **	(\$)	58,013
Total program expenditures since beginning of permit coverage	(\$)	218,258
Funding mechanism(s) (General Fund, Enterprise, Utility, etc)		General Fund

#### **Education, Involvement, and Training**

Estimated number of property owners reached by education program(s)	(# or %)	100%
Stormwater management committee established	(y/n)	У
Stream teams established or supported	(# or y/n)	n
Shoreline clean-up participation or quantity of shoreline miles cleaned **	(y/n or mi.)	n
Shoreline cleaned since beginning of permit coverage	(mi.)	n
Household Hazardous Waste Collection Days		
days sponsored **	(#)	n
<ul> <li>community participation **</li> </ul>	(# or %)	n
material collected **	(tons or gal)	n
School curricula implemented	(y/n)	У

## Legal/Regulatory

	In Place	Reviewing		Draft	
	Prior to	Existing		in	
	Phase II	Authorities	Drafted	Review	Adopted
Regulatory Mechanism Status (indicate with "X")					
<ul> <li>Illicit Discharge Detection &amp; Elimination</li> </ul>					X
<ul> <li>Erosion &amp; Sediment Control</li> </ul>					X
<ul> <li>Post-Development Stormwater Management</li> </ul>					X
Accompanying Regulation Status (indicate with "X")					
<ul> <li>Illicit Discharge Detection &amp; Elimination</li> </ul>					X
<ul> <li>Erosion &amp; Sediment Control</li> </ul>					X
<ul> <li>Post-Development Stormwater Management</li> </ul>					Х

## Mapping and Illicit Discharges

	(Preferred Uni	ts) Response
Outfall mapping complete	(%)	100
Estimated or actual number of outfalls	(#)	27
System-Wide mapping complete (complete storm sewer infrastructure)	(%)	100
Mapping method(s)		
<ul> <li>Paper/Mylar</li> </ul>	(%)	100
<ul> <li>CADD</li> </ul>	(%)	0
<ul> <li>GIS</li> </ul>	(%)	0
Outfalls inspected/screened **	(# or %)	100
Outfalls inspected/screened (Since beginning of permit coverage)	(# or %)	100
Illicit discharges identified **	(#)	2
Illicit discharges identified (Since beginning of permit coverage)	(#)	3
Illicit connections removed **	(#); and	0
	(est. gpd)	
Illicit connections removed (Since beginning of permit coverage)	(#); and	0
	(est. gpd)	
% of population on sewer	(%)	20
% of population on septic systems	(%)	80

#### Construction

(Preferred Units) Response Number of construction starts (>1-acre) \*\* (#) 5 Estimated percentage of construction starts adequately regulated for erosion and sediment control \*\* (%) 100% Site inspections completed \*\* 100% (# or %) Tickets/Stop work orders issued \*\* (# or %) 0 Fines collected \*\* 0 (# and \$) Complaints/concerns received from public \*\* (#) 1

#### Post-Development Stormwater Management

Estimated percentage of development/redevelopment projects adequately regulated for post-	(%)	100
construction stormwater control		
Site inspections (for proper BMP installation & operation) completed **	(# or %)	100%
BMP maintenance required through covenants, escrow, deed restrictions, etc.	(y/n)	у
Low-impact development (LID) practices permitted and encouraged	(y/n)	n

#### **Operations and Maintenance**

Average frequency of catch basin cleaning (non-commercial/non-arterial streets) **	(times/yr)	2
Average frequency of catch basin cleaning (commercial/arterial or other critical streets) **	(times/yr)	1
Qty of structures cleaned **	(#)	765
Qty. of storm drain cleaned **	(%, LF or	100
	mi.)	
Qty. of screenings/debris removed from storm sewer infrastructure **	(lbs. or tons)	Est 350 tons
Disposal or use of screenings (landfill, POTW, compost, beneficial use, etc.) **	(location)	Landfill
		compost

Basin Cleaning Costs		
<ul> <li>Annual budget/expenditure (labor &amp; equipment)**</li> </ul>	(\$)	58,013
Hourly or per basin contract rate **	(\$/hr or \$ per basin)	6,400/basin
<ul> <li>Disposal cost**</li> </ul>	(\$)	0
Cleaning Equipment		
• Clam shell truck(s) owned/leased	(#)	1
• Vacuum truck(s) owned/leased	(#)	0
Vacuum trucks specified in contracts	(y/n)	n
% Structures cleaned with clam shells **	(%)	100
% Structures cleaned with vactor **	(%)	0

	(Preferred Units	s) Response
Average frequency of street sweeping (non-commercial/non-arterial streets) **	(times/yr)	2
Average frequency of street sweeping (commercial/arterial or other critical streets) **	(times/yr)	1
Qty. of sand/debris collected by sweeping **	(lbs. or tons)	Est 700 tons
Disposal of sweepings (landfill, POTW, compost, beneficial use, etc.) **	(location)	Land fill , compost pipe bedding
Annual Sweeping Costs		
<ul> <li>Annual budget/expenditure (labor &amp; equipment)**</li> </ul>	(\$)	1,335.09
• Hourly or lane mile contract rate **	(\$/hr. or ln mi.)	47.67/hr
Disposal cost**	(\$)	0
Sweeping Equipment		
Rotary brush street sweepers owned/leased	(#)	1
Vacuum street sweepers owned/leased	(#)	0
Vacuum street sweepers specified in contracts	(y/n)	0
% Roads swept with rotary brush sweepers **	%	100
<ul> <li>% Roads swept with vacuum sweepers **</li> </ul>	%	0

Reduction (since beginning of permit coverage) in application on public land of:		
("N/A" = never used; "100%" = elimination)		
<ul> <li>Fertilizers</li> </ul>	(lbs. or %)	Never used
<ul> <li>Herbicides</li> </ul>	(lbs. or %)	Never used
<ul> <li>Pesticides</li> </ul>	(lbs. or %)	Never used
Integrated Pest Management (IPM) Practices Implemented	(y/n)	у

	(Preferred Units	) Response
Average Ratio of Anti-/De-Icing products used **	% NaCl % CaCl <sub>2</sub>	15%
(also identify chemicals and ratios used in specific areas, e.g., water supply protection areas)	% MgCl <sub>2</sub> % CMA % Kac % KCl % Sand	85%
Pre-wetting techniques utilized **	(y/n or %)	n
Manual control spreaders used **	(y/n or %)	У
Zero-velocity spreaders used **	(y/n or %)	n
Estimated net reduction or increase in typical year salt/chemical application rate	(±lbs/ln mi. or %)	No change
Estimated net reduction or increase in typical year sand application rate **	(±lbs/ln mi. or %)	No change
% of salt/chemical pile(s) covered in storage shed(s)	(%)	100
Storage shed(s) in design or under construction	(y/n or #)	n
100% of salt/chemical pile(s) covered in storage shed(s) by May 2008	(y/n)	у

## Water Supply Protection

Installed or planned treatment BMPs for public drinking water supplies and their protection areas	# or y/n	n
Treatment units induce infiltration within 500-feet of a wellhead protection area	# or y/n	n

#### Addendum # 1

#### 1. Public Education and Outreach

During this year, Bristol County Agricultural High School offers a course of students, Watershed Management. Students have built and evaluated a rain garden. During the next year they will be taking samples to determine phosphates an nitrates. The Town has purchased test bottles. The Town will continue to work with Bristol County Agriculture High School regarding Storm Water.