Municipality/Organization:	Town of Dighton, Ma
EPA NPDES Permit Number:	MAR041105
MassDEP Transmittal Number	: W-040738
Annual Report Number	Year 11
& Reporting Period:	April 1, 2013 – March 31, 2014

NPDES PII Small MS4 General Permit Annual Report (Due: May 1, 2014)

Part I. General Information

Contact Person: Thomas J. Pires	Title:	Board of Selectmen/ Board of Health
Telephone #: (508) 669-6431		Email: debpi54@comcast.net
Mailing Address: 979 Somerset Ave Dighton, Ma 027	715	

Certification:

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature:	
Printed Name:	Thomas J. Pires
Title:	Chairman Board of Health
Date:	5/3/2014

Part II. Self-Assessment

Part III. Summary of Minimum Control Measures

1. Public Education and Outreach

BMP ID #	BMP Description Continue working with schools to get info out	Responsible Dept./Person Name Thomas J. Pires	Measurable Goal(s) Expansion of Program	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any) Storm Water is still part of the curriculum in local schools. Bristol	Planned Activities Students from Bristol County Agricultural High school will
Revised	to public			County Agricultural High School curriculum alignment effort demanded considerable faculty time and effort which left less for cooperative projects	continue to identify and map coordinates of outfalls in their area.
1-2	Provide storm water info in public area at Town Hall	Thomas J. Pires	Continue to have information on Stormwater available in Town Hall for the Public	Ongoing	Ongoing
Revised					

1-3	Work on methods of getting info out to the public re: storm water	Thomas J. Pires	Continue to explore new sources to educate public on importance of Storm water monitoring and control	Information remains available in public buildings within the town, Storm water addressed on local cable television and during Selectmen's Meeting	Continue to pursue new way of getting information out to public

2. Public Involvement and Participation

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
2-1 Revised	Research infiltration basins for stormwater disposal and management	Board of Health Planning Board	To conduct site visits semi- annually of existing above or below ground systems to ensure they are being maintained and functioning properly	The type of system to be installed for Storm water control still rest with the Planning Board and Consulting Engineer.	Board of Health and Planning Board will continue to monitor systems. Will modify as situation or regulation change.
Revised			<u>-</u>		
Revised					

3. Illicit Discharge Detection and Elimination

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
3-1 Revised	Review existing outfall maps and update as needed	Highway Supt.		We continue to monitor basins annually.	Awarded by Mass Department of Health an Intern. The Intern will collect all GPS Coordinates of catch basins and outflows to be uploaded.
3-2 Revised	Detect and eliminate discharges	Highway Supt.	Check for any new discharge sites	No new discharge sites located by Storm Drain System Cleaning by Highway Dept. Employees	Continue to monitor
3-3 Revised	Conduct illicit Discharge Education program	Highway Supt.	Review illicit discharge training with new employees	Covered as part of on the job training for new hires	Task Completed
3-4 Revised	Check on By- Law implementation	Thomas J. Pires	Monitor size of disturbed area that requires permit.	Size of area disturbed that requires a permit remains at 35,000 sq.ft	Continue to monitor and adjust if necessary
3-5	Check on implementation of storm water regulation	Thomas J. Pires	Investigated and resolved one complaint of storm water violations. Found not to be a violation.	Continue to investigate all complaints of potential violations and enforce by law if necessary	Frequency of violations has been reduced due to the awareness of Storm water.
Revised					
Revised					

4. Construction Site Stormwater Runoff Control

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
4-1	Revise Site Plan, Review section of Zoning Bylaw	Planning Board	Explore and implement Storm Water Control	No Revisions required	Task Completed and On Going Review
Revised					
4-2	Review procedures for receipt and consideration of information submitted by the public	Board of Health Planning Board Conservation Commission	Propose changes in By- Law regulation resulting from ongoing monitoring or input from residents	Change in land disturbance are approved by Boards and Voters	Task Completed
Revised					
4-3	Revise Site Inspection and Enforcement Control Measures	Board of Health Planning Board Conservation Commission	Investigation and site visit for all potential violations	Investigated and resolved one complaint	We continue to monitor all construct and land disturbance areas covered by the By – law
Revised	program	Commission			
Revised					
Revised					
Revised					

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
5-1	Review to see if need to modify Zoning By-law	Planning Board	Continue to monitor Storm water by-law conflicts with Zoning By-law or if Storm Water by- law caused any permitting difficulties.	No conflicts found that resulted in permitting difficulties during this reporting period	On going
Revised					
5-2	Revise Subdivision Rules and Regulations	Planning Board	Review Subdivision Rules and Regulations to determine if revision is needed	Review complete for reporting period and no revision needed. No problems encountered or conflicts with existing subdivision rules and regulations and	Ongoing
Revised				storm water by- law and regulations	
5-3.1 Revised	Ensure adequate Long term O&M of BMP'S	Highway Supt Thomas J. Pires	Annual Review process used to determine if O&m of BMP;s are practical in application or if there need to be changes in conditions or processes during reporting period	Completed Review. No major problems detected.	Ongoing
Revised					
5-3.2	Ensure Adequate Long- term O&M BMP'S	Planning Board	Any proposed change or revisions in 5-3.1 above will be discussed with the Planning Board and any other appropriate Board or Commission	No action required during reporting period	Task Completed
Revised					

5. Post-Construction Stormwater Management in New Development and Redevelopment

Revised	 		
Revised	 		

6. Pollution Prevention and Good Housekeeping in Municipal Operations

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
6-1 Revised	Educated Municipal Employees	Highway Superintendent	Update Employee training	Town has updated training program on stormwater management including methods for spotting problems, illicit discharges or suspicious storm drain discharges.	Ongoing
6-2 Revised	Develop & Implement plan to prevent and reduce pollutant runoff from municipal operations	Highway Superintendent	Continue work on Municipal Operations stormwater Plan (MOSP) needed	Town continues to work toward development of MOSP. The Town continues to review and expand MOSP	Ongoing
6-3	Catch Basin Cleaning	Highway Superintendent	Clean and inspect all catch basins annually	Town purchased a catch basin cleaning truck and will continue to conduct	Annual Catch basin cleaning will continue
Revised				catch basin cleaning annually	
6-4	Street Sweeping	Highway Superintendent	Continue to perform on all Town Roads bi- annually	Street Sweeping was conducted on some of the Streets due to the late spring we will continue to sweep all	Street Sweeping of all Town Roads will continue bi-annually
Revised				Town roads	
Revised					
Revised					

BMP ID #	BMP Description	Responsible Dept./Person Name	Measurable Goal(s)	Progress on Goal(s) – Permit Year 11 (Reliance on non-municipal partners indicated, if any)	Planned Activities
Revised					

7. BMPs for Meeting Total Maximum Daily Load (TMDL) Waste Load Allocations (WLA) <<i f applicable>>

7a. Additions

7b. WLA Assessment

Part V. Program Outputs & Accomplishments (OPTIONAL)

(Since beginning of permit coverage unless specified otherwise by a **, which indicates response is for period covering April 1, 2012 through March 31, 2013)

Programmatic

			Response
Stormwater management position created/staffed	((y/n)	У
Annual program budget/expenditures **	(Preferre	St)Units)	56,985
Total program expenditures since beginning of permit coverage	((\$)	275,158
Funding mechanism(s) (General Fund, Enterprise, Utility, etc)			General Fund

Education, Involvement, and Training

Estimated number of property owners reached by education program(s)	(# or %)	100%
Stormwater management committee established	(y/n)	У
Stream teams established or supported	(# or y/n)	n
Shoreline clean-up participation or quantity of shoreline miles cleaned **	(y/n or mi.)	n
Shoreline cleaned since beginning of permit coverage	(mi.)	n
Household Hazardous Waste Collection Days		
days sponsored **	(#)	n
 community participation ** 	(# or %)	n
material collected **	(tons or gal)	n
School curricula implemented	(y/n)	У

Legal/Regulatory

	In Place Prior to	Reviewing Existing		
	Phase II	Authorities	Drafted Drafterview	
Regulatory Mechanism Status (indicate with "X")			Review	Adoptad
Illicit Discharge Detection & Elimination				Adopted
 Erosion & Sediment Control 				X
 Post-Development Stormwater Management 				
Accompanying Regulation Status (indicate with "X")				
 Illicit Discharge Detection & Elimination 				X
 Erosion & Sediment Control 				X
 Post-Development Stormwater Management 				

Mapping and Illicit Discharges

			Response
Outfall mapping complete		(%)	100
Estimated or actual number of outfalls	(Prefe	rred Units)	27
System-Wide mapping complete (complete storm sewer infrastructure)		(%)	100
Mapping method(s)		•	
 Paper/Mylar 		(%)	100
• CADD x		(%)	0
 GIS 		(%)	0
Outfalls inspected/screened **		(# or %)	100
Outfalls inspected/screened (Since beginning of permit coverage)		(# or %)	100
Illicit discharges identified **		(#)	2
Illicit discharges identified (Since beginning of permit coverage) X		(#)	3
Illicit connections removed **		(#); and	0
		(est. gpd)	
Illicit connections removed (Since beginning of permit coverage)		(#); and	0
		(est. gpd)	
% of population on sewer		(%)	20
% of population on septic systems		(%)	80

Construction

Response

	Response
(#)	5
rred Units)	100%
(# or %)	100%
(# or %)	0
(# and \$)	0
(#)	1
	(# or %) (# or %) (# or %) (# and \$)

Post-Development Stormwater Management

Estimated percentage of development/redevelopment projects adequately regulated for post-	(%)	100
construction stormwater control		
Site inspections (for proper BMP installation & operation) completed **	(# or %)	100%
BMP maintenance required through covenants, escrow, deed restrictions, etc.	(y/n)	у
Low-impact development (LID) practices permitted and encouraged	(y/n)	n

Operations and Maintenance

Average frequency of catch basin cleaning (non-commercial/non-arterial streets) **	(times/yr)	2
Average frequency of catch basin cleaning (commercial/arterial or other critical streets) **	(times/yr)	1
Qty of structures cleaned **	(#)	765
Qty. of storm drain cleaned **	(%, LF or	100
	mi.)	
Qty. of screenings/debris removed from storm sewer infrastructure **	(lbs. or tons)	Est 650 tons
Disposal or use of screenings (landfill, POTW, compost, beneficial use, etc.) **	(location)	Landfill
		compost

Basin Cleaning Costs		
 Annual budget/expenditure (labor & equipment)** 	(\$)	58,013
Hourly or per basin contract rate **	(\$/hr or \$ per basin)	6,400/basin
 Disposal cost** 	(\$)	0
Cleaning Equipment		
• Clam shell truck(s) owned/leased	(#)	1
• Vacuum truck(s) owned/leased	(#)	0
Vacuum trucks specified in contracts	(y/n)	n
% Structures cleaned with clam shells **	(%)	100
% Structures cleaned with vactor **	(%)	0

	Response
(times/yr)	2
Preferred hereits)	1
(lbs. or tons)	Est 700 tons
(location)	Land fill,
	compost pipe
	bedding
(\$)	1,335.09
(\$/hr. or	47.67/hr
ln mi.)	
(\$)	0
(#)	1
(#)	0
(y/n)	0
%	100
%	0
	Prefer real Lisits) (lbs. or tons) (location) (location) (%) (\$) (\$/hr. or (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$) (\$)

Response

Reduction (since beginning of permit coverage) in application on public land of:		
("N/A" = never used; "100%" = elimination)		
 Fertilizers 	(lbs. or %)	Never used
 Herbicides 	(lbs. or %)	Never used
 Pesticides 	(lbs. or %)	Never used
Integrated Pest Management (IPM) Practices Implemented	(y/n)	у

			Response
Average Ratio of Anti-/De-Icing products used **	(Prefe	% NaCl red Lipits)	15%
(also identify chemicals and ratios used in specific areas, e.g., water supply protection areas)		% MgCl ₂ % CMA % Kac % KCl % Sand	85%
Pre-wetting techniques utilized **		(y/n or %)	n
Manual control spreaders used **		(y/n or %)	у
Zero-velocity spreaders used **		(y/n or %)	n
Estimated net reduction or increase in typical year salt/chemical application rate		(±lbs/ln mi. or %)	No change
Estimated net reduction or increase in typical year sand application rate **		(±lbs/ln mi. or %)	No change
% of salt/chemical pile(s) covered in storage shed(s)		(%)	100
Storage shed(s) in design or under construction		(y/n or #)	n
100% of salt/chemical pile(s) covered in storage shed(s) by May 2008		(y/n)	у

Water Supply Protection

Storm water outfalls to public water supplies eliminated or relocated	# or y/	/n	n
-----------------------------------------------------------------------	---------	----	---

_

20

Installed or planned treatment BMPs for public drinking water supplies and their protection areas	# or y/n	n
Treatment units induce infiltration within 500-feet of a wellhead protection area	# or y/n	n

Addendum # 1

1. Public Education and Outreach

The Massachusetts Vocational Technical Curriculum Frameworks were reviewed during the summer of 2012. The Natural Resource Management and Environmental Science curriculum frameworks experienced drastic revision and improvement which will resulted in a more appropriate and rigorous frameworks. The Bristol County Agricultural High School Natural Resource Management (NRM) Department faculty has been diligently working to adjust their curriculum in order to achieve alignment with the draft (i.e., new) vocational curriculum frameworks. This curriculum alignment effort demanded considerable faculty time and effort which left less for cooperative projects, such as the Dighton Storm Water Mapping and Monitoring work.