

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Hull, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles	Cause	TMDL
				In Town - Total	Total	In Town - Total		
MA70-01_2008	Boston Harbor	Boston Harbor	5	17.58	15490.32		Pathogens Priority organics	
MA70-06_2008	Hingham Bay	Boston Harbor	5	5.76	611.76		Pathogens	
MA70-07_2008	Hingham Bay	Boston Harbor	5	42.66	3070.72		Pathogens	
MA70-09_2008	Hull Bay	Boston Harbor	5	35.66	1591.39		Pathogens	
MA74-11_2008	Weir River	Boston Harbor:	5	65.94	529.69		Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries