

EPA Official Record

Notes ID: 36E7E03295C7732285257AD80070F82A

From: Jay Borkland <jborkland@apexcos.com>

To: Phil Colarusso/R1/USEPA/US@EPA; "Chet Myers" <cmyers@apexcos.com>

Copy To: Cynthia Catri/R1/USEPA/US@EPA; Ann Williams/R1/USEPA/US@EPA

Delivered Date: 11/09/2012 04:22 PM EST

Subject: RE: Water Quality Mixing zone

ATTACHMENT: image002.png

ATTACHMENT: image003.png

Yes, it is clear - its consistent with what was discussed on the conference call we all had. That is the definition we will be using for the project. Thanks. - J

[IMAGE]

Jay Borkland

Apex Companies, LLC

125 Broad Street, 5th Floor

Boston, MA 02110

O) 617-728-0070 x111 M) 617-513-0640

Follow Apex on [IMAGE] and Like us on [IMAGE]

Privacy Notice: This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have

received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

From: colarusso.phil@epamail.epa.gov [mailto:colarusso.phil@epamail.epa.gov]
Sent: Friday, November 09, 2012 3:52 PM
To: Jay Borkland; Chet Myers
Cc: Catri.Cynthia@epamail.epa.gov; Williams.Ann@epamail.epa.gov
Subject: Water Quality Mixing zone

Jay, Chet,

Just a quick clarification, which you guys may not need, but just in case. Ann had written in her Performance Standards summary a clause about a 400 foot mixing zone. Just so there is no confusion, this does dovetail with the monitoring program and the need to meet performance standards 200 foot downstream from the dredge. We view the mixing zone as a circle with a 200 foot radius and the dredge being on the centerpoint. Thus, the diameter of the circle is 400 feet. If this is not clear, please call me at (617) 918-1506. If it is understood, please just give me a quick reply.

Thanks
Phil

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

- image002.png - image003.png