

EPA Official Record

Notes ID: 08BFA0361964D2C585257AD800705CBE

From: Chet Myers <cmyers@apexcos.com>

To: Phil Colarusso/R1/USEPA/US@EPA

Copy To: Carl Dierker/R1/USEPA/US@EPA; Ann Williams/R1/USEPA/US@EPA; Cynthia Catri/R1/USEPA/US@EPA; "Davis, Gary (DCR)" <gary.davis@state.ma.us>; Jackie Leclair/R1/USEPA/US@EPA; Jay Borkland <jborkland@apexcos.com>; Mike Marsh/R1/USEPA/US@EPA; "Sneeringer, Paul J NAE" <Paul.J.Sneeringer@usace.army.mil>

Delivered Date: 10/22/2012 03:53 PM EST

Subject: RE: South Terminal -- Additional Comments on Draft Mitigation Plans

ATTACHMENT: image002.png

ATTACHMENT: image003.png

Thanks for the clarification, Phil!

Chet

[IMAGE]

Chet Myers

Apex Companies, LLC

125 Broad Street, 5th Floor

Boston, MA 02110

O) 617-728-0070 x113 M) 617-908-5778

Follow Apex on [IMAGE] and Like us on [IMAGE]

Privacy Notice: This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

From: colarusso.phil@epamail.epa.gov [mailto:colarusso.phil@epamail.epa.gov]
Sent: Monday, October 22, 2012 3:47 PM
To: Chet Myers
Cc: Dierker.Carl@epamail.epa.gov; Williams.Ann@epamail.epa.gov;
Catri.Cynthia@epamail.epa.gov; Davis, Gary (DCR);
Leclair.Jackie@epamail.epa.gov; Jay Borkland; marsh.mike@epamail.epa.gov;
Sneeringer, Paul J NAE
Subject: Re: South Terminal -- Additional Comments on Draft Mitigation Plans

Chet,

One point of clarification on our comments from Friday evening. Our comments from Friday state that clean material from CAD Cell #3 must be used for winter flounder spawning mitigation. We understand that clean material from CAD Cell #3 is being used for capping of CAD Cell #2 and the "burrow pit" and thus we are not requiring it to be used for the flounder mitigation site. We apologize for any confusion and if you have any questions call me at (617) 918-1506.

Phil

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

***** ATTACHMENT NOT DELIVERED *****

This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED *****

- image002.png - image003.png