


# National Copper Products Dowagiac, Michigan

(not to scale)



This drawing shows some of the areas where contaminated ground water originated. The contamination was caused by Sunstrand Heat Transfer, now National Copper Products. Much of the ground water under the facility and west, north and northwest of the site is contaminated with trichloroethylene and other chemicals.