

DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION

Interim Final 2/5/99

RCRA Corrective Action

Environmental Indicator (EI) RCRIS code (CA750)

Migration of Contaminated Groundwater Under Control

Facility Name: The Dow Chemical Company - La Porte Site
 Facility Address: P.O. Box 685 (550 Battleground Road), La Porte, TX 77572-0685
 Facility EPA ID#: TXD000017756

1. Has all available relevant/significant information on known and reasonably suspected releases to the groundwater media, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

If yes - check here and continue with #2 below.

If no - re-evaluate existing data, or

if data are not available, skip to #8 and enter "IN" (more information needed) status code.

BACKGROUND**Definition of Environmental Indicators (for the RCRA Corrective Action)**

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Migration of Contaminated Groundwater Under Control" EI

A positive "Migration of Contaminated Groundwater Under Control" EI determination ("YE" status code) indicates that the migration of "contaminated" groundwater has stabilized, and that monitoring will be conducted to confirm that contaminated groundwater remains within the original "area of contaminated groundwater" (for all groundwater "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Migration of Contaminated Groundwater Under Control" EI pertains ONLY to the physical migration (i.e., further spread) of contaminated ground water and contaminants within groundwater (e.g., non-aqueous phase liquids or NAPLs). Achieving this EI does not substitute for achieving other stabilization or final remedy requirements and expectations associated with sources of contamination and the need to restore, wherever practicable, contaminated groundwater to be suitable for its designated current and future uses.

Duration / Applicability of EI Determinations

EI Determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e.,

RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

Migration of Contaminated Groundwater Under Control
Environmental Indicator (EI) RCRIS code (CA750)

Page 2

2. Is **groundwater** known or reasonably suspected to be “**contaminated**”¹ above appropriately protective “levels” (i.e., applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action, anywhere at, or from, the facility?

If yes - continue after identifying key contaminants, citing appropriate “levels,” and referencing supporting documentation.

If no - skip to #8 and enter “YE” status code, after citing appropriate “levels,” and referencing supporting documentation to demonstrate that groundwater is not “contaminated.”

If unknown - skip to #8 and enter “IN” status code.

Rationale and Reference(s):

Ground water is known to be contaminated primarily with chlorobenzene and aniline. The highest levels of contamination are associated with the former waste water treatment units in the southeastern corner of the facility, with low levels of contaminants in nearby off-site wells. The Compliance plan issued December 16, 2003 specifies the monitoring program as well as the Protective Concentration Levels (PCLs) to be achieved as the remedial goal throughout the plume.

These protective concentrations are as follows;

Chlorobenzene = 0.100 mg/L

Aniline = 0.160 mg/L

Additional data can be obtained in the semi-annual groundwater reports referenced on Page 8.

Footnotes:

¹“Contamination” and “contaminated” describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriate “levels” (appropriate for the protection of the groundwater resource and its beneficial uses).

Migration of Contaminated Groundwater Under Control
Environmental Indicator (EI) RCRIS code (CA750)

Page 3

3. Has the **migration** of contaminated groundwater **stabilized** (such that contaminated groundwater is expected to remain within “existing area of contaminated groundwater”² as defined by the monitoring locations designated at the time of this determination)?

X If yes - continue, after presenting or referencing the physical evidence (e.g., groundwater sampling/measurement/migration barrier data) and rationale why contaminated groundwater is expected to remain within the (horizontal or vertical) dimensions of the “existing area of groundwater contamination”².

If no (contaminated groundwater is observed or expected to migrate beyond the designated locations defining the “existing area of groundwater contamination”²) - skip to #8 and enter “NO” status code, after providing an explanation.

If unknown - skip to #8 and enter “IN” status code.

Rationale and Reference(s):

Ground water concentration data for the areas of concern are presented in the semi-annual ground water monitoring reports submitted pursuant to Compliance Plan # 50253. The recent reports document that the ground water recovery systems that are in place (consisting of recovery wells and trenches) are adequately controlling the migration of contaminated ground water. Ground water concentrations in the off-site wells have exhibited some statistical noise but indicate that the existing ground water recovery systems are containing any potential migration of the contaminated ground water plume. Specifically, the following ground water monitoring reports were used to make this Environmental Indicator code determination;

January 25, 2001, July 26, 2001, January 18, 2002, July 22, 2002, January 23, 2003, and July 24, 2003.

² “existing area of contaminated groundwater” is an area (with horizontal and vertical dimensions) that has been verifiably demonstrated to contain all relevant groundwater contamination for this determination, and is defined by designated (monitoring) locations proximate to the outer perimeter of “contamination” that can and will be sampled/tested in the future to physically verify that all “contaminated” groundwater remains within this area, and that the further migration of “contaminated” groundwater is not occurring. Reasonable allowances in the proximity of the monitoring locations are permissible to incorporate formal remedy decisions (i.e., including public participation) allowing a limited area for natural attenuation.

Migration of Contaminated Groundwater Under Control
Environmental Indicator (EI) RCRIS code (CA750)

Page 4

4. Does “contaminated” groundwater **discharge** into **surface water** bodies?

_____ If yes - continue after identifying potentially affected surface water bodies.

X If no - skip to #7 (and enter a “YE” status code in #8, if #7 = yes) after providing an explanation and/or referencing documentation supporting that groundwater “contamination” does not enter surface water bodies.

_____ If unknown - skip to #8 and enter “IN” status code.

Rationale and Reference(s):

The semi-annual ground water monitoring reports referenced in question 3 document that the extent of contaminated ground water does not extend near any surface water bodies.

Migration of Contaminated Groundwater Under Control
Environmental Indicator (EI) RCRIS code (CA750)

Page 7

7. Will groundwater **monitoring** / measurement data (and surface water/sediment/ecological data, as necessary) be collected in the future to verify that contaminated groundwater has remained within the horizontal (or vertical, as necessary) dimensions of the “existing area of contaminated groundwater?”

If yes - continue after providing or citing documentation for planned activities or future sampling/measurement events. Specifically identify the well/measurement locations which will be tested in the future to verify the expectation (identified in #3) that groundwater contamination will not be migrating horizontally (or vertically, as necessary) beyond the “existing area of groundwater contamination.”

If no - enter “NO” status code in #8.

If unknown - enter “IN” status code in #8.

Rationale and Reference(s):

RCRA Compliance Plan # 50253 specifies the monitoring program and sampling and analysis plan that Dow must continue to implement until such time that all ground water is remediated to the PCLs described on page 2. This compliance plan requires the sampling and analysis of specific wells and outlines the reporting requirements to be addressed in each of the semi-annual reports to be submitted. Any changes to the monitoring well network or sampling and analysis plan will require prior approval by the TCEQ. The well locations and analytical program can be found in the Compliance Plan issued December 16, 2003

Migration of Contaminated Groundwater Under Control
Environmental Indicator (EI) RCRIS code (CA750)

Page 8

8. Check the appropriate RCRIS status codes for the Migration of Contaminated Groundwater Under Control EI (event code CA750), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).

 X YE - Yes, "Migration of Contaminated Groundwater Under Control" has been verified. Based on a review of the information contained in this EI determination, it has been determined that the "Migration of Contaminated Groundwater" is "Under Control" at the Dow Chemical Company facility, EPA ID # **TXD000017756**, located in La Porte Texas. Specifically, this determination indicates that the migration of "contaminated" groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the "existing area of contaminated groundwater" This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

 NO - Unacceptable migration of contaminated groundwater is observed or expected.

 IN - More information is needed to make a determination.

Completed by _____
Mark E. Erwin
Senior Project Manager

Date: January 20, 2004

Supervisor _____
Cathy Remmert

State of Texas (EPA Region 6)

Date _____

Locations where References may be found:

Documents referenced within may be found at the TCEQ Central Office Record Services at 12100 Park 35 Circle, Austin, TX 78753

Contact telephone and e-mail numbers

Mark E. Erwin
512-312-2605
merwin@tceq.state.tx.us

Final Note: The purpose of the Migration of Contaminated Groundwater EI is to verify that the groundwater plume is stable. A "YE" determination does not constitute a screening tool to end the corrective action process. The "YE" determination may be changed at any time as new information becomes available.

