

Note: This is a reference cited in *AP 42, Compilation of Air Pollutant Emission Factors, Volume I Stationary Point and Area Sources*. AP42 is located on the EPA web site at [www.epa.gov/ttn/chief/ap42/](http://www.epa.gov/ttn/chief/ap42/)

The file name refers to the reference number, the AP42 chapter and section. The file name "ref02\_c01s02.pdf" would mean the reference is from AP42 chapter 1 section 2. The reference may be from a previous version of the section and no longer cited. The primary source should always be checked.

**AP-42 Section Number:** 9.9.4

**Reference Number:** 4

**Title:** Written correspondence from W. Cobb, American Alfalfa Processors Association, to T. Campbell, Midwest Research Institute, Updated alfalfa dehydration process diagram

Cobb, W.

American Alfalfa Processors  
Association

May 1995

**American Alfalfa Processors Association**

9948 West 87th Street, Suite E  
Overland Park, Kansas 66212  
Telephone 913-648-6800

AP-42 Section 9.9.4  
Reference 4  
Report Sect. \_\_\_\_\_  
Reference \_\_\_\_\_



May 18, 1995

Mr. Tom Campbell  
Midwest Research Institute  
401 Harrison Oaks Boulevard - Suite 350  
Cary, NC 27513

Dear Tom:

Enclosed is an updated generalized flow diagram for alfalfa dehydration plants. The secondary meal collector has been deleted from the present diagram, and a bag filter added to the grinder discharge air stream.


If you have any questions, or need additional information, please let us know.

Sincerely,

A handwritten signature in cursive script, appearing to read "Wanda L. Cobb".

Wanda L. Cobb  
Executive Vice President

enc



2-1. Generalized flow diagram for alfalfa dehydration plant.