

5.7 Calculation of Measured Butadiene Concentrations. Calculate the concentration of butadiene in the field samples using the detector responses as set forth in EPA Method 18.

7. BIBLIOGRAPHY

1. Federal Register, 51, No. 62, pp 11021-11022, April 1, 1986.
2. Method 18: Measurement of Gaseous Organic Compound Emissions by Gas Chromatography, 40 CFR Part 60, July 1, 1987.