

List of Companies and Personnel Certified in 2012 by EPA OAQPS to do PSD Audits for NAAQS Gases Through The Probe (TTP) :

Research Triangle Institute: Jeff Nichols (Lead), Steve Walters

EEMS: Eric Hebert (Lead), Sandy Grenville (subcontractor)

For any details or questions, call the EPA Regional NPAP contacts for EPA Region 8(Joshua Rickard; at rickard.joshua@epa.gov) and Region 10 (Christopher Hall; at hall.christopher@epa.gov).

Information about EPA PSD QA Requirements is provided in an EPA guidance document at :

<http://www.epa.gov/ttn/amtic/files/PSDAppAQATechNote14dec12.pdf>