

**KEEP
LIGHTS
AND**

FIRES AWAY!

USDA REG. NO. 218-139

**DANFORTH
CHLORINE**

HANDLE CAREFULLY

ACTIVE INGREDIENT	99.5%
CHLORINE	0.5%
INERT INGREDIENT	100%

**This car must not be next to a car
Explosives
Avoid contact with less
Corrosive
Beware**

ACCEPTED

JUN 16 1972

UNDER THE FEDERAL INSECTICIDE
FUNGICIDE AND RODENTICIDE ACT
FOR DANFORTH CHLORINE REGISTERED
ED UNDER NO. 218-139 SUBJECT
TO ATTACHED COMMENTS

BEST AVAILABLE COPY

AND
ES AWAY!

USDA REG. NO. 218-139

CHLORINE

HANDLE CAREFULLY

ACTIVE INGREDIENT	99.5%
CHLORINE	0.5%
INERT INGREDIENT	100%

This car must not be next to a car containing
Explosives
Avoid contact with leaking acid or
Corrosive liquid
Beware of fumes or
vapors!

WHEN LADING IS REMOVED
THIS PLACARD MUST
BE REMOVED
OR REVERSED

ACCEPTED

JUN 16 1972

UNDER THE FEDERAL INSECTICIDE
FUNGICIDE AND RODENTICIDE ACT
FOR ECONOMIC POISON REGISTERED
ED UNDER NO. 218-139 SUBJECT
TO ATTACHED COMMENTS

BEST AVAILABLE COPY

**KEEP
LIGHTS & FIRES
AWAY**

**THIS CAR CONTAINS
FLAMMABLE
or POISONOUS VAPOR
or CORROSIVE RESIDUE**

DANGEROUS

**DO NOT
INHALE VAPOR**

**DO NOT
ALLOW LIQUID OR SOLID
RESIDUE TO TOUCH SKIN**

**Securely replace manhole cover with a bar,
and the bottom outlet cap with a wrench
having a handle at least 48 in. long.**


DO NOT ENTER TANK

until it has been cleaned in accordance with the shippers instructions. DO NOT reload in transit with any commodity other than that shown on waybill or routing card.

BEST AVAILABLE COPY

EMPTY

COPY



ALL THE VALVES ON THIS CAR WERE IN WORKING ORDER WHEN THE CAR WAS LOADED WITH LIQUID CHLORINE. LIQUID AND GAS VALVES WERE CLEANED, DRIED AND REPACKED.

DO NOT OIL THE VALVES.

PACKING GLAND NUTS MAY BE SLIGHTLY LOOSE. IT IS NECESSARY TO RELIEVE A TIGHT VALVE. RETIGHTEN PROMPTLY TO AVOID A LEAK.

USE 11/16" WRENCH ON PACKING GLAND NUT. DO NOT USE WRENCH LONGER THAN 11/16" ON VALVE.

DO NOT LET DISCHARGE LINE STRAIN ON VALVE.


SEE OTHER SIDE

SEE INSTRUCTIONS ON OTHER SIDE

CHLORINE IS A TOXIC GAS UNDER PRESSURE. KEEP OUT OF REACH OF CHILDREN. HANDLE AND USE ONLY IN ACCORDANCE WITH INSTRUCTIONS ON THIS CARD.

SEE OTHER SIDE

937 24 100



ALL THE VALVES ON THIS CAR WERE IN WORKING ORDER WHEN THE CAR WAS LOADED WITH LIQUID CHLORINE. LIQUID AND GAS VALVES WERE CLEANED, OILED AND REPACKED EACH YEAR.

DO NOT OIL THE VALVES.

PACKING GLAND NUTS MAY BE SLIGHTLY LOOSE IF NECESSARY. TO RELIEVE A TIGHT VALVE, RETIGHTEN PROMPTLY TO AVOID A LEAK.

USE 11/16" WRENCH ON PACKING GLAND NUT. DO NOT USE WRENCH LONGER THAN 15" TO TIGHTEN VALVE.

DO NOT LET DISCHARGE LINE STRAIN ON VALVE.

SEE OTHER SIDE

DANGER! HAZARDOUS LIQUID AND GAS UNDER PRESSURE
 KEEP OUT OF REACH OF CHILDREN
 HANDLE AND USE ONLY IN ACCORDANCE WITH
 INSTRUCTIONS ON THIS CARD.

SEE OTHER SIDE
 FOR INSTRUCTIONS AND
 WARNING STATEMENT

NET WEIGHT

SCA 1430

BEST AVAILABLE COPY