



**LEGEND**


- Monitoring Well - GW Quality and Water Levels
- Monitoring Well - Water Levels Only
- Site Boundary and Fence Line

Chromium Concentration (mg/L)

- 0.1 - 1
- 1 - 10
- >10

**NOTES**

Aerial photograph taken ca. 2004.  
 Multiple structures have been deconstructed since the aerial photograph was taken.



**CORRECTIVE MEASURES STUDY  
 COLUMBIA MANUFACTURING COMPANY  
 RESTORATION PROJECT  
 WESTFIELD, MASSACHUSETTS**

**DISTRIBUTION OF CHROMIUM  
 SOUTH END GROUNDWATER - MAY 2009**

DRAWN BY: TLH	SCALE AS NOTED	PROJECT NO.: 71360.27
CHECKED BY: BCB	APPROVED BY: MAM	DATE: 2009

**RMT**  
 Patewood Plaza One, Suite 100  
 30 Patewood Drive  
 Greenville, SC 29615-3535  
 Phone: 864-281-0030  
 FAX: 864-281-0288