Close File

LEGEND

- Monitoring Well - GW Quality and Water Levels
- Monitoring Well - Water Levels Only
- Site Boundary and Fence Line

Cis-1,2-DCE Concentration (mg/L)

- 0.07 - 0.1
- >0.1

NOTES

Aerial photograph taken ca. 2004.
Multiple structures have been deconstructed since the aerial photograph was taken.

0 150 300
Feet

CORRECTIVE MEASURES STUDY
COLUMBIA MANUFACTURING COMPANY
RESTORATION PROJECT
WESTFIELD, MASSACHUSETTS

DISTRIBUTION OF CIS-1,2-DICHLOROETHENE
SOUTH END GROUNDWATER - MAY 2009

DRAWN BY: TLH	SCALE AS NOTED	PROJECT NO.: 71360.27
CHECKED BY: BCB	APPROVED BY: MAM	DATE: 2009

RMT
Patewood Plaza One, Suite 100
30 Patewood Drive
Greenville, SC 29615-3535
Phone: 864-281-0030
FAX: 864-281-0288

Map Document: (P:\Hydro\71360\ArcGIS9\July2009Reports\Distribution of cis-12-DCE South End Groundwater May2009.mxd)
7/31/2009 -- 10:17:44 AM