

Soil Site Restoration Activities (Interim Corrective Measures [ICMs] and Current Conditions)

Table 1
Status of SWMUs and AOCs

SWMU (S) OR AOC (A) NO.	UNIT NAME/DESCRIPTION/ GENERAL LOCATION	ACTION COMPLETED	FINAL REMEDY
S01	Nickel wastewater treatment tank	Removed	NFA
S02	Chrome wastewater treatment tank #1	Removed	NFA
S03	Chrome wastewater treatment tank #2	Removed	NFA
S04	Wastewater treatment tank floor spills	Remediated	NFA
S05	Zinc wastewater treatment tank	Removed	NFA
S06	Mixing tank	Removed	NFA
S07	WWTP filter press	Removed	NFA
S08	WWTP filter press hoppers	Removed	NFA
AO9	Sludge roll-off boxes	Removed	NFA
A10	Nickel filter	Removed	NFA
A11	pH adjustment tank (old)	Removed	NFA
A12	Storage tank 11	Removed	NFA
S13	Drum storage room (in vicinity of vapor degreasing)	Remediated	MNA and AULs
A14	Hazardous waste drum storage	Remediated	NFA
S15	Scrap metal roll-off	Removed	NFA
A16	Reflecting pond	Remediated and Capped	MNA and AULs
A17	Storm sewer	Remediated	MNA and AULs
A18	Sanitary sewer	Remediated	MNA and AULs
S19	Paint waste accumulation area at Building 1 Third Floor	Removed	NFA
S20	Paint waste accumulation area at Warehouse Building 13	Removed	NFA
A21	Storage yard run-off area	Capped	MNA and AULs
S22	Distillation tanks	Removed	NFA
A23	Stripping area floor drains	Remediated	MNA and AULs
S24	Nickel transfer tank	Removed	NFA
S25	Chrome transfer tank #1	Removed	NFA
S26	Chrome transfer tank #2	Removed	NFA
S27	Chrome 2 transfer tank #1	Removed	NFA

Soil Site Restoration Activities (Interim Corrective Measures [ICMs] and Current Conditions)

Table 1
Status of SWMUs and AOCs

SWMU (S) OR AOC (A) NO.	UNIT NAME/DESCRIPTION/ GENERAL LOCATION	ACTION COMPLETED	FINAL REMEDY
S28	Nickel reclamation tank	Removed	NFA
A29	Former lagoons	Remediated and Capped	MNA and AULs
A30	Underground discharge pipe	Removed	NFA
S31	Polishing baghouse	Removed	NFA
S32	Furniture polishing baghouse	Removed	NFA
A33	Former incinerator / scrap metal fill area	Removed	NFA
A34	Fire pond	Remediated and Capped	MNA and AULs
A35	Removed UST west of Building 11	Removed	MNA and AULs
A36	Abandoned UST at Building 1	Removed	MNA and AULs
A37	Fuel storage area	Removed, Remediated, and Capped	MNA and AULs
S38	Old degreaser	Removed	NFA
A39	Old trenches and sumps	Remediated and Capped	MNA and AULs
A40	Pickling room drain and sump	Remediated	MNA
A41	Zinc plating line trench and sump	Remediated and Capped	MNA and AULs
A42	Nickel and chrome plating line sump	Remediated and Capped	MNA and AULs
S43	Decanting tanks	Removed	
A44	Rim room	Remediated and Capped	MNA and AULs
A45	Wastewater treatment pipes		In operation.
A46	Wastewater treatment room sump		In operation.
A47	Gasoline UST	Removed	NFA
A48	Abandoned UST at Building 2	Removed	NFA
A49	Rack maintenance area	Removed	NFA
A50	UST at Building 1 – 1A	Removed	NFA
A51	UST at alley between Building 3 and Building 4	Removed	MNA and AULs
A52	UST at Building 17 east of Building 4	Closed in place	NFA

NFA = No Further Action

MNA = Monitored Natural Attenuation

AULs = Activity and Land Use Limitations