




LEGEND

- GW Quality and Water Levels
- Water Levels Only
- Site Boundary and Fence Line

NOTES

Aerial photograph taken ca. 2004.
 Multiple structures have been deconstructed since the aerial photograph was taken.



CORRECTIVE MEASURES STUDY COLUMBIA MANUFACTURING COMPANY RESTORATION PROJECT WESTFIELD, MASSACHUSETTS		
SOUTH END GROUNDWATER MONITORED NATURAL ATTENUATION MONITORING NETWORK		
DRAWN BY:	TLH	SCALE AS NOTED
PROJECT NO.:	00-71360.27	
CHECKED BY:	BCB	APPROVED BY: MAM
DATE:	JULY 2009	
RMT		Patewood Plaza One, Suite 100 30 Patewood Drive Greenville, SC 29615-3535 Phone: 864-281-0030 FAX: 864-281-0288