



SDMS DocID

557617

ROUTE

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-1

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1100

**Description:** LD = West; Mumford River, dam, Covitch Building  
No. 19 and No. 23 to right.

112



25  
11

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-2

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1101

**Description:** LD = East; Mumford River, flowing beneath Covitch Building No. 26

11  
25



5 2 '86

R17N

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-3

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1105

**Description:** LD = North; debris pile, stained soil and drum lid along edge of parking lot on south side of Mumford River, opposite Covitch Building No. 19.

13



E.T.

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-4

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1110

**Description:** LD = West; three metal and one plastic empty 55-gallon drums located in overgrown area adjacent to parking lot on south side of Mumford River, opposite Building No. 19.

E.T.



RTI

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-5

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1110

**Description:** LD = North; two metal and one plastic empty 55-gallon drums located in overgrown area adjacent to parking lot on south side of Mumford River, opposite Building No. 19.

RTI



RT  
T

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-6

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1112

**Description:** LD = Southwest; demolition debris pile, adjacent to parking lot south side of Mumford River, opposite Covitch Building No. 19.

1112



R1T2

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-7

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1120

**Description:** LD = West; fine dark color material in the alleged former coal ash area south of Douglas Road.

112



RTT

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-8

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1121

**Description:** LD = North; view of Raceway intake as seen from Douglas Road.

12



5 2'96

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-9

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1135

**Description:** LD = East; Monitoring Well M-8, southwest of  
Covitch Building No. 16.

11-1-96



R11

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-10

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1136

**Description:** LD = Southeast; unsecured/open monitoring well M-9; also note coal ash/foundry sand fill, typical of Arcade Property east and south of Arcade Building.

MN2



EST

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-11

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1137

**Description:** LD = Northwest; unsecured/open monitoring well M-10. Note: Coal ash/foundry sand fill material/brown in color on Arcade Property east of Arcade Building.

M 12



RJ

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-12

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1138

**Description:** LD = North; unsecured/open monitoring Well M-11.

**Note:** Lack of vegetation and coal ash/foundry sand fill material on Arcade Property east of Arcade Building.

01 M 2



5 21 96

RTN

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-13

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1140

**Description:** LD = Northwest; Monitoring Well M-6, on Arcade Property east of building. Note: Dark color vegetation-free area beyond first row of trees.

1-13



R11

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-14

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1143

**Description:** LD = East-Northeast; Monitoring Well M-7, located on the Arcade Property, east of Arcade Building. Note: Variation in cover material and lack of vegetation.

R11



5-2-86

2-15

RITZ 564 656099 0741 N N N-12

RECEIVED  
FEB 15 1954  
COMMUNICATIONS SECTION

RECEIVED  
FEB 15 1954  
COMMUNICATIONS SECTION

RECEIVED  
FEB 15 1954  
COMMUNICATIONS SECTION



2  
1  
1  
1

**Site Name:** Covitch Property / Former ATF Davidson Co.

**Location:** Northbridge, MA

**Photo:** 2-16

**CERCLIS No.:** MAD046128559

**TDD No.:** 95-07-0065

**Photographer:** M. Jennings

**Date:** 2 May 1996

**Time:** 1147

**Description:** LD = Southwest; Monitoring Well M-5 located on the Arcade Property southeast of Arcade Building. Note: Mumford River in background.

2  
1  
1  
1



RJ TZ 304 0293091 014: 0000-12

