



# Waterbody Assessment and TMDL Status Abington, MA

0 0.5 Miles

Map produced by EPA Region I GIS Center  
Map Tracker ID 6678, February 25, 2010  
Data Sources: TeleAtlas, Census Bureau, USGS, MassDEP

<p><b>Waterbody Label</b></p> <p>State ID, Waterbody Name (Category) (TMDL(s) approved for this waterbody)</p> <p>See companion table for a listing of pollutants, non-pollutants, and TMDLs for each waterbody</p>	<p><b>Assessment of Waterbody Segment</b></p> <ul style="list-style-type: none"> <li>Category 2: Attaining some uses; other uses not assessed</li> <li>Category 3: Insufficient information to make assessments for any use.</li> </ul>	<ul style="list-style-type: none"> <li>Category 4a: TMDL is completed and approved for one or more pollutants</li> <li>Category 4c: Impairment not caused by a pollutant.</li> <li>Category 5: Impaired or threatened for one or more uses and requiring a TMDL.</li> </ul>	<ul style="list-style-type: none"> <li>Waterbodies</li> <li>Swamp/Marsh</li> <li>MS4 Urbanized Areas (2000 Census)</li> <li>Municipal Boundaries</li> </ul>
---	---	---	---