



Waterbody Assessment and TMDL Status Danvers, MA



Map produced by EPA Region I GIS Center
Map Tracker ID 6678, February 25, 2010
Data Sources: TeleAtlas, Census Bureau,
USGS, MassDEP

<p>Waterbody Label</p> <p>State ID, Waterbody Name (Category) (TMDL(s) approved for this waterbody)</p>	<p>Assessment of Waterbody Segment</p> <ul style="list-style-type: none"> Category 2: Attaining some uses; other uses not assessed Category 3: Insufficient information to make assessments for any use. 	<ul style="list-style-type: none"> Category 4a: TMDL is completed and approved for one or more pollutants Category 4c: Impairment not caused by a pollutant. Category 5: Impaired or threatened for one or more uses and requiring a TMDL. 	<ul style="list-style-type: none"> Waterbodies Swamp/Marsh MS4 Urbanized Areas (2000 Census) Municipal Boundaries
--	---	---	---

See companion table for a listing of pollutants, non-pollutants, and TMDLs for each waterbody