

Waterbody Assessment and TMDL Status Medford, MA



Map produced by EPA Region I GIS Center Map Tracker ID 6678, February 25, 2010 Data Sources: TeleAtlas, Census Bureau, USGS, MassDEP

Waterbody Label

State ID, Waterbody Name (Category) (TMDL(s) approved for this waterbody)

See companion table for a listing of pollutants, non-pollutants, and TMDLs for each waterbody

Assessment of Waterbody Segment

Category 2: Attaining some uses; other uses

Category 3: Insufficient information to make assessments for any use.

Category 4a: TMDL is completed and approved for one or more pollutants

Category 4c: Impairment not caused by a pollutant.

Category 5: Impaired or threatened for one or more

Waterbodies

Swamp/Marsh

MS4 Urbanized Areas (2000 Census)

Municipal Boundaries