

Waterbody Assessment and TMDL Status
Milford, MA

N

0 0.5 Miles

EPA

Map produced by EPA Region I GIS Center
Map Tracker ID 6678, February 25, 2010
Data Sources: TeleAtlas, Census Bureau, USGS, MassDEP

Waterbody Label

State ID,
Waterbody Name (Category)
(TMDL(s) approved for this waterbody)

See companion table for a listing of pollutants, non-pollutants, and TMDLs for each waterbody

Assessment of Waterbody Segment

- Category 2: Attaining some uses; other uses not assessed
- Category 3: Insufficient information to make assessments for any use.
- Category 4a: TMDL is completed and approved for one or more pollutants
- Category 4c: Impairment not caused by a pollutant.
- Category 5: Impaired or threatened for one or more uses and requiring a TMDL.

- Waterbodies
- Swamp/Marsh
- MS4 Urbanized Areas (2000 Census)
- Municipal Boundaries