

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Avon, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA62-07_2008	Trout Brook	Taunton	5			0.3	3.4	Organic enrichment/Low DO Pathogens Siltation Suspended solids Turbidity	
MA62023_2008	Brockton Reservoir	Taunton	4c	89.4	89.4				
MA62201_2008	Waldo Lake	Taunton	4c	44.39	72.39				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

Category 2 - Attaining some uses; other uses not assessed
 Category 3 - Insufficient information to make assessments for any use
 Category 4a - TMDL is completed
 Category 4c - Impairment not caused by a pollutant
 Category 5 - Impaired or threatened for one or more uses and requiring a TMDL