

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Bedford, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA82A-07_2008	Concord River	Concord	5			1.8	10.4	Exotic species* Metals Nutrients Pathogens	
MA83-01_2008	Shawsheen River	Shawsheen	5			1.6	1.6	Organic enrichment/Low DO Pathogens	CN122.0
MA83-05_2008	Elm Brook	Shawsheen	5			2.5	5.0	Other habitat alterations* Pathogens Turbidity	CN122.0
MA83-06_2008	Vine Brook	Shawsheen	4a			1.1	6.9	Pathogens	CN122.0
MA83-08_2008	Shawsheen River	Shawsheen	5			1.4	2.1	Other habitat alterations* Pathogens	CN122.0
MA83-10_2008	Kiln Brook	Shawsheen	4a			0.1	1.5	Pathogens	CN122.0

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Bedford, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA83-14_2008	Spring Brook	Shawsheen	4a			2.5	2.6		
								Pathogens	CN122.0
MA83-17_2008	Shawsheen River	Shawsheen	5			2.7	5.7		
								Organic enrichment/Low DO	
								Pathogens	CN122.0
MA83004_2008	Fawn Lake	Shawsheen	3	11.82	11.82				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries