

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Berlin, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA82B-04_2008	Assabet River	Concord	5			1.3	8.0		
								Cause Unknown	
								Metals	
								Noxious aquatic plants	CN201.0
								Nutrients	CN201.0
								Organic enrichment/Low DO	CN201.0
								Pathogens	
MA82B-10_2008	Gates Pond Brook	Concord	3			1.0	1.0		
MA82B-21_2008	North Brook	Concord	2			6.4	7.8		
MA82047_2008	Gates Pond	Concord	3	72.67	72.67				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries