

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Boylston, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA81-29_2008	Malagasco Brook	Nashua	5			2.4	2.4	Cause Unknown Organic enrichment/Low DO Pathogens	
MA81-34_2008	Unnamed Tributary (Boylston Bro	Nashua	5			0.5	0.5	Cause Unknown	
MA82B-18_2008	Cold Harbor Brook	Concord	2			1.3	6.1		
MA51110_2008	Newton Pond	Blackstone	4c	20.11	53.68			Noxious aquatic plants	CN070.1
MA51122_2008	Pout Pond	Blackstone	3	14.03	14.03				
MA51191_2008	Sewall Pond	Blackstone	3	12.71	12.71				
MA81147_2008	Wachusett Reservoir	Nashua	4a	2218.96	3966.55			Mercury	NEHgTMDL
MA82095_2008	Rocky Pond	Concord	4c	61.83	61.83				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

Category 2 - Attaining some uses; other uses not assessed
 Category 3 - Insufficient information to make assessments for any use
 Category 4a - TMDL is completed
 Category 4c - Impairment not caused by a pollutant
 Category 5 - Impaired or threatened for one or more uses and requiring a TMDL