

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Burlington, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA83-06_2008</i>	Vine Brook	Shawsheen	4a			4.3	6.9		
								Pathogens	CN122.0
<i>MA83-11_2008</i>	Long Meadow Brook	Shawsheen	4a			1.3	1.3		
								Pathogens	CN122.0
<i>MA83-13_2008</i>	Sandy Brook	Shawsheen	4a			1.2	1.2		
								Pathogens	CN122.0
<i>MA92-04_2008</i>	Maple Meadow Brook	Ipswich	4c			0.1	4.2		
<i>MA83003_2008</i>	Butterfield Pond	Shawsheen	5	2.97	2.97			Noxious aquatic plants Turbidity	
<i>MA92041_2008</i>	Mill Pond	Ipswich	4a	59.09	59.09			Mercury	NEHgTMDL

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries