

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Canton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA73-01_2008</i>	Neponset River	Boston Harbor:	5			0.4	13.3	Metals Noxious aquatic plants Nutrients Organic enrichment/Low DO Pathogens Priority organics Siltation Suspended solids Turbidity	CN121.0
<i>MA73-02_2008</i>	Neponset River	Boston Harbor:	5			1.3	8.4	Metals Objectionable deposits* Oil and grease Organic enrichment/Low DO Pathogens Priority organics Turbidity	CN121.0
<i>MA73-05_2008</i>	East Branch	Boston Harbor:	5			3.2	3.2	Cause Unknown Flow alteration*	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Canton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
								Metals Organic enrichment/Low DO Pathogens Thermal modifications	CN121.0
MA73-18_2008	Steep Hill Brook	Boston Harbor:	2			0.1	0.9		
MA73-20_2008	Beaver Meadow Brook	Boston Harbor:	5			2.3	3.6	Organic enrichment/Low DO Pathogens	CN121.0
MA73-21_2008	Massapoag Brook	Boston Harbor:	5			1.5	4.2	Cause Unknown Nutrients	
MA73-22_2008	Pequid Brook	Boston Harbor:	5			4.1	4.1	Organic enrichment/Low DO Pathogens	CN121.0
MA73-25_2008	Pecunit Brook	Boston Harbor:	2			1.8	1.8		
MA73-27_2008	Ponkapog Brook	Boston Harbor:	4a			3.1	3.1	Pathogens	CN121.0

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Canton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles	Cause	TMDL
				In Town - Total	Total	In Town - Total		
MA73005_2008	Bolivar Pond	Boston Harbor:	5	19.79	19.79		Turbidity	
MA73020_2008	Forge Pond	Boston Harbor:	5	8	8		Turbidity	
MA73022_2008	Glen Echo Pond	Boston Harbor:	3	10.18	15.75			
MA73043_2008	Ponkapoag Pond	Boston Harbor:	4c	108.67	213.78			
MA73048_2008	Reservoir Pond	Boston Harbor:	4c	251.32	251.32			

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries