

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Dighton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA62-52_2008	Muddy Cove Brook	Taunton	3			2.0	2.0		
MA62-53_2008	Segreganset River	Taunton	4c			5.9	7.9		
MA62-54_2008	Segreganset River	Taunton	4c			0.4	0.4		
MA62-56_2008	Three Mile River	Taunton	5			0.8	12.8		
								Pathogens	
MA62-02_2008	Taunton River	Taunton	5	0	183.61				
								Pathogens	
MA62-03_2008	Taunton River	Taunton	5	0	591.87				
								Organic enrichment/Low DO	
								Pathogens	
MA62122_2008	Mount Hope Mill Pond	Taunton	4c	6.72	45.18				
MA62124_2008	Muddy Cove Brook Pond	Taunton	5	23.24	23.24				
								Noxious aquatic plants	
								Turbidity	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Dighton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles	Cause	TMDL
				In Town - Total	Total	In Town - Total		
MA62-50_2008	Broad Cove	Taunton	5	56.84	80.64		Pathogens	
MA62-51_2008	Muddy Cove Brook	Taunton	5	0	5.06		Pathogens	
MA62-55_2008	Segreganset River	Taunton	5	0	12.72		Pathogens	
MA62-57_2008	Three Mile River	Taunton	5	0	13.8		Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries