

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Gardner, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA35-06_2008	Otter River	Millers	2			1.9	4.3		
MA35-07_2008	Otter River	Millers	5			2.3	4.4	Nutrients Organic enrichment/Low DO Other habitat alterations* Turbidity	
MA35007_2008	Bents Pond	Millers	4a	6.16	6.16			Noxious aquatic plants Turbidity	CN123.2 CN123.2
MA35013_2008	Cowee Pond	Millers	3	18.26	18.26			Nutrients	CN123.2
MA35014_2008	Crystal Lake	Millers	3	142.26	142.26				
MA35021_2008	Dunn Pond	Millers	2	18	18				
MA35029_2008	Hilchey Pond	Millers	4a	7.61	7.61			Turbidity	CN123.2

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Gardner, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles	Cause	TMDL
				In Town - Total	Total	In Town - Total		
MA35034_2008	Kendall Pond	Millers	3	21.91	21.91			
MA35056_2008	Parker Pond	Millers	4c	32.19	32.19		Flow alteration* Noxious aquatic plants	CN123.2
MA35059_2008	Perley Brook Reservoir	Millers	3	54.68	54.68			
MA35062_2008	Ramsdall Pond	Millers	4a	2.14	2.14		Noxious aquatic plants	CN123.2
MA35104_2008	Wrights Reservoir	Millers	3	107.71	130.85		Nutrients	CN123.2
MA81151_2008	Lake Wampanoag	Nashua	4a	67.68	224.47		Mercury	NEHgTMDL

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries