

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Granby, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA34-07_2008	Bachelor Brook	Connecticut	4a			7.9	11.6		
								Nutrients	
MA34-19_2008	Stony Brook	Connecticut	5			5.2	13.3		
								Exotic species*	
								Noxious aquatic plants	
								Pathogens	
								Turbidity	
MA34-23_2008	Weston Brook	Connecticut	5			0.3	2.7		
								Nutrients	
MA34024_2008	Forge Pond	Connecticut	5	72.04	72.04				
								Exotic species*	
								Noxious aquatic plants	
								Nutrients	
MA34037_2008	Ingraham Brook Pond	Connecticut	4c	4.62	4.62				
								Exotic species*	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries