

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Hadley, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA34-04_2008	Connecticut River	Connecticut	5			5.7	34.4	Pathogens PCBs	
MA34-25_2008	Mill River	Connecticut	5			2.8	5.2	Pathogens	
MA34-27_2008	Fort River	Connecticut	5			6.1	12.8	Pathogens	
MA34-31_2008	Unnamed Tributary	Connecticut	3			0.5	0.5		
MA34098_2008	Lake Warner	Connecticut	4c	65.13	65.13			Exotic species* Noxious aquatic plants Nutrients Organic enrichment/Low DO Turbidity	CN112.0 CN112.0 CN112.0 CN112.0

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

Category 2 - Attaining some uses; other uses not assessed
 Category 3 - Insufficient information to make assessments for any use
 Category 4a - TMDL is completed
 Category 4c - Impairment not caused by a pollutant
 Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries