

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Holbrook, MA

| ID           | Waterbody Name | Watershed Name | Category | Acres           |       | Miles           |       | Cause  | TMDL |
|--------------|----------------|----------------|----------|-----------------|-------|-----------------|-------|--|------|
|              |                |                |          | In Town - Total | Total | In Town - Total | Total |  |      |
| MA74-06_2008 | Cochato River  | Boston Harbor: | 5        |                 |       | 1.0             | 4.2   | Organic enrichment/Low DO<br>Pathogens<br>Pesticides |      |
| MA74-12_2008 | Trout Brook    | Boston Harbor: | 3        |                 |       | 1.2             | 1.2   |  |      |
| MA74013_2008 | Lake Holbrook  | Boston Harbor: | 5        | 31.17           | 31.17 |                 |       | Noxious aquatic plants                               |      |
| MA74021_2008 | Sylvan Lake    | Boston Harbor: | 5        | 5.85            | 5.85  |                 |       | Pesticides<br>Priority organics                      |      |

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries