

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Lexington, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA72-28_2008	Beaver Brook	Charles	5			1.4	5.5	Exotic species* Flow alteration* Noxious aquatic plants Nutrients Organic enrichment/Low DO Other habitat alterations* Pathogens Siltation Taste, odor and color Turbidity	CN156.0
MA83-06_2008	Vine Brook	Shawsheen	4a			1.4	6.9	Pathogens	CN122.0
MA83-10_2008	Kiln Brook	Shawsheen	4a			1.5	1.5	Pathogens	CN122.0
MA72014_2008	Cambridge Reservoir	Charles	3	37.39	532.02				
MA72156_2008	Cambridge Reservoir, Upper Basin	Charles	5	40.35	44			Noxious aquatic plants Turbidity	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries