

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Lunenburg, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA81-16_2008	Catacoonamug Brook	Nashua	3			0.0	3.3		
MA81-22_2008	Mulpus Brook	Nashua	3			7.6	11.3		
MA81031_2008	Hickory Hills Lake	Nashua	4a	309.82	309.82			Mercury	NEHgTMDL
MA81080_2008	Massapoag Pond	Nashua	2	64.32	64.32				
MA81122_2008	Lake Shirley	Nashua	5	359.44	359.9			Noxious aquatic plants Turbidity	
MA81154_2008	Lake Whalom	Nashua	4c	94.69	96.38				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries