

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Manchester-by-the-Sea, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA93-29_2008	Cat Brook	North Coastal	5			1.7	1.7	Pathogens pH Siltation	
MA93-47_2008	Causeway Brook	North Coastal	5			1.1	1.1	Pathogens	
MA93-19_2008	Manchester Harbor	North Coastal	5	14.45	212.97			Pathogens	
MA93-25_2008	Salem Sound	North Coastal	5	0.67	5140.36			Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries