

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Rehoboth, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA52-11_2008	Coles Brook	Ten Mile	4c			0.6	4.2		
								Flow alteration*	
MA53-04_2008	Palmer River	Narragansett Bay (Shore)	5			5.3	5.3		
								Flow alteration*	
								Nutrients	
								Pathogens	CN182.0
MA53-05_2008	Palmer River	Narragansett Bay (Shore)	4a			0.0	0.0		
								Pathogens	CN182.0
MA53-07_2008	West Branch Palmer River	Narragansett Bay (Shore)	2			3.8	3.8		
								Pathogens	CN182.0
MA53-08_2008	East Branch Palmer River	Narragansett Bay (Shore)	3			7.1	7.1		
MA53-09_2008	Rumney Marsh Brook	Narragansett Bay (Shore)	3			1.3	1.3		
MA53-10_2008	Beaverdam Brook	Narragansett Bay (Shore)	3			2.9	2.9		
MA53-11_2008	Bad Luck Brook	Narragansett Bay (Shore)	3			1.7	1.7		

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## Rehoboth, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA53-12_2008	Fullers Brook	Narragansett Bay (Shore)	3			1.1	1.7		
MA53-13_2008	Clear Run Brook	Narragansett Bay (Shore)	4a			0.3	1.6	Pathogens	CN182.0
MA53-14_2008	Torrey Creek	Narragansett Bay (Shore)	3			0.7	2.6		
MA53-15_2008	Oak Swamp Brook	Narragansett Bay (Shore)	3			3.0	3.0		
MA53-16_2008	Rocky Run	Narragansett Bay (Shore)	4a			7.6	8.7	Pathogens	CN182.0
MA53-03_2008	Palmer River	Narragansett Bay (Shore)	4a	0.55	67.69			Pathogens	CN182.0
MA53-05_2008	Palmer River	Narragansett Bay (Shore)	4a	53.61	53.87			Pathogens	CN182.0

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries