

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Rockport, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA93-26_2008	Alewife Brook	North Coastal	3			0.2	1.0		
MA93011_2008	Cape Pond	North Coastal	5	42.45	42.45			Turbidity	
MA93053_2008	Quarry Reservoir	North Coastal	3	7.44	7.44				
MA93064_2008	Rum Rock Lake	North Coastal	3	9.62	9.62				
MA93-17_2008	Rockport Harbor	North Coastal	5	0.18	15.66			Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries