

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Russell, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA32-05_2008	Westfield River	Westfield	5			5.1	17.8	Cause Unknown Noxious aquatic plants Taste, odor and color Turbidity	
MA32-21_2008	Bradley Brook	Westfield	2			0.7	0.7		
MA32-22_2008	Potash Brook	Westfield	2			3.5	5.2		
MA32-35_2008	Little River	Westfield	2			2.6	2.6		
MA32-36_2008	Little River	Westfield	5			1.7	5.8	Siltation	
MA32018_2008	Cobble Mountain Reservoir	Westfield	3	11.86	1033.78				
MA32061_2008	Russell Pond	Westfield	2	82.18	82.18				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries