

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Scituate, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA94-18_2008	Bound Brook	South Coastal	5			1.1	2.2	Flow alteration* Turbidity	
MA94-25_2008	First Herring Brook	South Coastal	2			2.7	3.9		
MA94-01_2008	Cohasset Harbor	South Coastal	5	27.15	445.22			Pathogens	
MA94-02_2008	Scituate Harbor	South Coastal	5	16.18	206.23			Pathogens	
MA94-05_2008	North River	South Coastal	5	12.8	193.56			Metals Pathogens	
MA94-06_2008	North River	South Coastal	5	0	355.38			Pathogens	
MA94-07_2008	Herring River	South Coastal	5	0	49.59			Pathogens	
MA94-09_2008	South River	South Coastal	5	29.23	400.41			Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Scituate, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA94113_2008	Old Oaken Bucket Pond	South Coastal	5	8.35	8.35			Noxious aquatic plants Nutrients	
MA94152_2008	Tack Factory Pond	South Coastal	2	8.07	8.07				
MA94178_2008	Aaron River Reservoir	South Coastal	4c	0.41	136.13			Flow alteration* Mercury	NEHgTMDL
MA94-19_2008	The Gulf	South Coastal	5	26.61	80.56			Pathogens	
MA94-32_2008	Cohasset Cove	South Coastal	5	0.86	55.46			Pathogens	
MA94-33_2008	Musquashcut Pond	South Coastal	5	69.81	69.81			Flow alteration* Noxious aquatic plants Nutrients Organic enrichment/Low DO Pathogens	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries