

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## South Hadley, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA34-04_2008	Connecticut River	Connecticut	5			2.6	34.4	Pathogens PCBs	
MA34-05_2008	Connecticut River	Connecticut	5			0.5	15.9	Pathogens PCBs Suspended solids	
MA34-07_2008	Bachelor Brook	Connecticut	4a			3.7	11.6	Nutrients	
MA34-19_2008	Stony Brook	Connecticut	5			5.4	13.3	Exotic species* Noxious aquatic plants Pathogens Turbidity	
MA34040_2008	Leaping Well Reservoir	Connecticut	5	8.81	8.81			Noxious aquatic plants	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries