

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Southampton, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA34-10_2008	Manhan River	Connecticut	3			1.6	6.6		
MA34-11_2008	Manhan River	Connecticut	5			11.2	19.2		
								Pathogens	
MA34-12_2008	Potash Brook	Connecticut	3			1.0	1.0		
MA34-16_2008	Tripple Brook	Connecticut	2			1.0	1.0		
MA34-17_2008	Moose Brook	Connecticut	2			2.6	2.6		
MA34-18_2008	Broad Brook	Connecticut	2			1.1	9.3		
MA32055_2008	Pequot Pond	Westfield	5	62.82	155				
								Nutrients	
								Organic enrichment/Low DO	
MA34089_2008	Tighe Carmody Reservoir	Connecticut	3	353.41	353.41				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries