

# Summary of Waterbody Assessment and TMDL Status in Massachusetts

## *Sterling, MA*

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
<i>MA81-30_2008</i>	East Wachusett Brook	Nashua	5			0.6	5.5		
								Pathogens	
<i>MA81-31_2008</i>	Stillwater River	Nashua	2			6.1	6.7		
<i>MA81035_2008</i>	East Waushacum Pond	Nashua	2	182.18	182.18				
<i>MA81060_2008</i>	Hy-Crest Pond	Nashua	2	104.06	104.06				
<i>MA81137_2008</i>	Stuart Pond	Nashua	4c	36.83	36.83				
<i>MA81147_2008</i>	Wachusett Reservoir	Nashua	4a	246.7	3966.55			Mercury	NEHgTMDL
<i>MA81153_2008</i>	West Waushacum Pond	Nashua	2	110.93	110.93				
<i>MA81170_2008</i>	The Quag	Nashua	3	31.8	31.8				

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>  
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>  
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

### Assessment of Waterbody Segment

Category 2 - Attaining some uses; other uses not assessed  
 Category 3 - Insufficient information to make assessments for any use  
 Category 4a - TMDL is completed  
 Category 4c - Impairment not caused by a pollutant  
 Category 5 - Impaired or threatened for one or more uses and requiring a TMDL