

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Whitman, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA62-09_2008	Beaver Brook	Taunton	5			0.1	6.8		
								Pathogens	
MA62-33_2008	Shumatuscasant River	Taunton	5			3.0	8.5		
								Organic enrichment/Low DO Other habitat alterations* Pathogens Siltation	
MA62-38_2008	Meadow Brook	Taunton	5			2.4	6.0		
								Pathogens	
MA62090_2008	Hobart Pond	Taunton	5	9.05	9.05				
								Turbidity	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

- Category 2 - Attaining some uses; other uses not assessed
- Category 3 - Insufficient information to make assessments for any use
- Category 4a - TMDL is completed
- Category 4c - Impairment not caused by a pollutant
- Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries