



**Figure 3.1-6: Waste Rock Pile 3 showing  
Acid Rock Drainage (orange stained  
areas) and dead vegetation  
Callahan Mining Superfund Site, Brooksville,  
Maine**



**Figure 3.1-7: Photo of Waste  
Rock Pile 3 showing Area of  
Slope Failure  
Callahan Mining Superfund Site,  
Brooksville, Maine**



**Figure 3.1-8: Photo of Waste  
Rock Pile 3 showing Area of  
Pre-cursor Slip Surface  
Callahan Mining Superfund Site,  
Brooksville, Maine**



**Figure 3.1-9: Photo of Dyer  
Cove  
Callahan Mining Superfund Site,  
Brooksville, Maine**



**Figure 3.1-10: Photo of Open Pit during Mining Operation Callahan Mining Superfund Site, Brooksville, Maine**



**Figure 3.1-11: Photo of Former  
Mining Pit  
Callahan Mining Superfund Site,  
Brooksville, Maine**