Click Here to Return to Index

Photo # 3 - April 12, 1995

(Same as Photo #2)

Drainage ditch near MW91-41.

Discharge from right bank into ditch.
(Discolored/"rusty" colored)

3292