

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of chain-link fence and bilingual warning sign installed on the NEC greenway. Allendale Pond is in the background. Photograph taken facing east.

FRAME NUMBER: 0 **DATE:** 14 December 1999 **TIME:** 10:35 **SKY CONDITION:** Cloudy
PHOTOGRAPH BY: Renata Wynnyk **WITNESS(ES):** None
CAMERA: Minolta **SETTING:** Automatic **FILM TYPE:** 35-mm **FILM ROLL:** BC100116



SCENE: Closeup view of chain-link fence and bilingual warning sign installed on the NEC greenway. Note Allendale pond and residential properties in the background. Photograph taken facing southeast.

FRAME NUMBER: 1 **DATE:** 14 December 1999 **TIME:** 10:36 **SKY CONDITION:** Cloudy
PHOTOGRAPH BY: Renata Wynnyk **WITNESS(ES):** None
CAMERA: Minolta **SETTING:** Automatic **FILM TYPE:** 35-mm **FILM ROLL:** BC100116


PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed cedar fence at 522/524 Woonasquatucket Avenue. Allendale Pond is located in the background. Photograph taken facing northwest.

FRAME NUMBER: 6 **DATE:** 14 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:57 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100116




SCENE: View of rip-rap being installed along the riverbank, after site trailers were demobilized. Photograph taken facing south.

FRAME NUMBER: 8 **DATE:** 15 December 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:33 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100116

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed chain-link fence at 34 Centredale Avenue. Photograph taken facing southeast.

FRAME NUMBER: 10 **DATE:** 15 December 1999

TIME: 11:45 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100116



SCENE: View of chain-link fence installed at 15 Centredale Avenue. Allendale Pond is located in the background. Photograph taken facing south.

FRAME NUMBER: 11 **DATE:** 15 December 1999

TIME: 11:47 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100116

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed chain-link fence at 15 Centredale Avenue extending west to 18 Aldrich Street. Photograph taken facing west.

FRAME NUMBER: 12 **DATE:** 15 December 1999


TIME: 11:50 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100116



SCENE: View of chain-link fence installed adjacent to Allendale Dam. Note Woonasquatucket River and Town Asphalt Company in the background. Photograph taken facing northwest.

FRAME NUMBER: 13 **DATE:** 15 December 1999

TIME: 11:55 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100116

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed chain-link fence restricting access to Allendale Dam. Photograph taken facing west.

FRAME NUMBER: 14 **DATE:** 15 December 1999

TIME: 11:57 **SKY CONDITION:** Cloudy

PHOTOGRAPH BY: Renata Wynnnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC100116

ALL NEGATIVES ARE LOCATED IN THE SITE FILE.

Appendix G

Photodocumentation Log

March 2000 - July 2000

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: Example of a multi-lingual/pictorial warning signs installed adjacent to Lymanville Pond.

FRAME NUMBER: 4 **DATE:** 29 March 2000
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:02 **SKY CONDITION:** Sunny
WITNESS(ES):
FILM TYPE: 35-mm **FILM ROLL:** BC100299




SCENE: Example of multi-lingual warning sign posted around Lymanville Pond.

FRAME NUMBER: 6 **DATE:** 29 March 2000
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:10 **SKY CONDITION:** Sunny
WITNESS(ES):
FILM TYPE: 35-mm **FILM ROLL:** BC100299

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of completed Interim Soil Cap No. 2 and asphalt patch on driveway, taken from the Brook Village building.

FRAME NUMBER: 20A **DATE:** 13 July 2000
PHOTOGRAPH BY: Jenifer Sullivan
CAMERA: Minolta **SETTING:** Automatic

TIME: 0915 **SKY CONDITION:** Sunny
WITNESS(ES):
FILM TYPE: 35-mm **FILM ROLL:** BC100456



SCENE: Closeup view of asphalt patch on the driveway between the Brook Village building and Centredale Manor.

FRAME NUMBER: 17A **DATE:** 13 July 2000
PHOTOGRAPH BY: Jenifer Sullivan
CAMERA: Minolta **SETTING:** Automatic

TIME: 0900 **SKY CONDITION:** Sunny
WITNESS(ES):
FILM TYPE: 35-mm **FILM ROLL:** BC100456