


PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island

TOP



SCENE: View of multilingual warning sign installed on the east side of the Manton Avenue dam. Note sign installed on the west side of the dam in the background. Photograph taken facing west.

FRAME NUMBER: 20A DATE: 1 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 12:20 SKY CONDITION: Cloudy
WITNESS(ES): Brad Bowen
FILM TYPE: 35-mm FILM ROLL: BC100432



SCENE: View of multilingual warning sign installed on the west side of the Dyerville Dam. Photograph taken facing east.


FRAME NUMBER: 22A DATE: 1 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 14:30 SKY CONDITION: Cloudy
WITNESS(ES): Brad Bowen
FILM TYPE: 35-mm FILM ROLL: BC100432

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island

TOP



SCENE: View of installed multilingual warning sign located off of Hillside Avenue. Note the Woonasquatucket River in the background. Photograph taken facing east.

FRAME NUMBER: 23A DATE: 1 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 15 15 SKY CONDITION: Cloudy
WITNESS(ES): Brad Bowen
FILM TYPE: 35-mm FILM ROLL: BC100432



SCENE: View of multilingual warning sign installed on the west side of the Manton Avenue Dam. Note the abandoned apartment complex in the background. Photograph taken facing east.

FRAME NUMBER: 24A DATE: 1 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 14:45 SKY CONDITION: Cloudy
WITNESS(ES): Brad Bowen
FILM TYPE: 35-mm FILM ROLL: BC100432

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of chain-link fence installation at Lee Romano Ballfield. Note the Woonasquatucket River in left background. Photograph taken facing north.

FRAME NUMBER: 01 **DATE:** 9 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:20 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400



SCENE: View of high visibility fence and chain-link fence installation in the batting cage area at Lee Romano ballfield. Photograph taken facing southeast

FRAME NUMBER: 02 **DATE:** 9 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:25 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of warning sign installed at the western end of Lymansville Dam (Johnston, RI side of the river). Photograph taken facing east.

FRAME NUMBER: 03 **DATE:** 9 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:30 **SKY CONDITION:** Sunny
WITNESS(ES): NA
FILM TYPE: 35-mm **FILM ROLL:** BC100400




SCENE: View of chain link-fence installation at Lee Romano Ballfield. Photograph taken facing east.

FRAME NUMBER: 04 **DATE:** 12 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:25 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400

PHOTOGRAPHY LOG SHEET


Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed chain-link fence in the batting cage area at Lee Romano ballfield. Photograph taken facing southeast.

FRAME NUMBER: 05 **DATE:** 12 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:27 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400



TOP

SCENE: View of installed security gate, adjacent to the snack bar building. Note Woonasquatucket River in background. Photograph taken facing east.

FRAME NUMBER: 06 **DATE:** 12 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:30 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400


PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of completed chain-link fence installation, with snack bar building at the extreme left. Photograph taken facing east.

FRAME NUMBER: 07 **DATE:** 12 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 11:35 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400




SCENE: Closeup view of the bottom fence rail, with the Woonasquatucket River in the background. Photograph taken facing east.

FRAME NUMBER: 10 **DATE:** 14 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:00 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of a warning sign, adjacent to the chain-link fence. Note the Allendale Mill Condominium building in background. Photograph taken facing north.

FRAME NUMBER: 12 **DATE:** 14 April 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12 20 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400



SCENE: View of wooded area south of the Centredale Manor building. Note shed at extreme left of photograph. Photograph taken facing east.

FRAME NUMBER: 14 **DATE:** 9 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:00 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400