

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of wooded area located southeast of the Centredale Manor parking lot. Photograph taken facing southeast.

FRAME NUMBER: 15 **DATE:** 9 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:02 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400




SCENE: View of wooded area directly south of the Centredale Manor parking lot. Photograph taken facing south.

FRAME NUMBER: 16 **DATE:** 9 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:03 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC100400

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island

TOP




SCENE: View of the rental Geoprobe unit during subsurface sampling of the south end of the parking lot. Photograph taken facing southwest.

FRAME NUMBER: 00 DATE: 22 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 09:40 SKY CONDITION: Sunny
WITNESS(ES): None
FILM TYPE: 35-mm FILM ROLL: BC300355

TOP



SCENE: Closeup view of rental Geoprobe sampling activities. Photograph taken facing west.

FRAME NUMBER: 01 DATE: 22 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 09:42 SKY CONDITION: Sunny
WITNESS(ES): None
FILM TYPE: 35-mm FILM ROLL: BC300355

PHOTOGRAPHY LOG SHEET


Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of command post, and decontamination trailers. The Woonasquatucket River is located behind the trailers, approximately 15 feet from the parking lot edge. Photograph taken facing northwest.

FRAME NUMBER: 02 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:30 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355




SCENE: View of cedar fence installation, facing west, adjacent to the Brook Village Parking Lot No. 5. Photograph taken facing west.

FRAME NUMBER: 03 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:35 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of installed cedar fencing. The Brook Village apartment building is located in the background. Photograph taken facing north.

FRAME NUMBER: 04 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:36 **SKY CONDITION:** Partly sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of Allendale Pond, adjacent to Allendale Dam. Note the residential property (518 Woonasquatucket Avenue) in the background. Photograph taken facing east.

FRAME NUMBER: 05 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:45 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of Allendale Pond. Note the low water levels in the Woonasquatucket River channel. Photograph taken facing north.

FRAME NUMBER: 06 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:47 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of Allendale Pond. Note low water levels and residential properties (Aldrich Street) in the background. Photograph taken facing northwest.

FRAME NUMBER: 07 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:50 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of Allendale Dam. Note the low water levels, debris in channel, and Town Asphalt Company in the background. Photograph taken facing west.

FRAME NUMBER: 08 **DATE:** 25 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:51 **SKY CONDITION:** Partly cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of partially cleared wooded area located south of the Centredale Manor building. Note shed in center of photograph. Photograph taken facing east.

FRAME NUMBER: 09 **DATE:** 29 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:20 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of partially cleared wooded area, located south of the Centredale Manor building. Photograph taken facing east.

FRAME NUMBER: 10 **DATE:** 29 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:21 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of the rental Geoprobe unit, sampling in the former "oxbow" area, located between Brook Village and Centredale Manor buildings, adjacent to the river. Note the Brook Village apartment building in the background. Photograph taken facing north.

FRAME NUMBER: 12 **DATE:** 29 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:43 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355