

Figure A.7. Results of bathymetric survey for depth to sediment within the HBHA Pond. Contours are shown at one meter intervals. The north (WN), central (WC), and south (WS) surface water sampling locations are also shown. Image was derived from April 2001 aerial photograph obtained from MassGIS.



Figure A.8. Surface water and sediment porewater monitoring locations within the Hall's Brook Holding Area Pond. Image was derived from November 1995 aerial photograph obtained from MassGIS.




Figure A.9. Location of sediment samples collected from Hall's Brook Holding Area Pond. Symbol notations: ▲ solids pumped from sediment-water interface, ● sediment cores collected using Geoprobe® coring device with 2" sleeves, ★ shallow grab samples. Image was derived from November 1995 aerial photograph obtained from MassGIS.

