

Appendix O
Project Photos



SAWYER STREET CDF

CRANE BARGE AND TUG

BELLC TEST DREDGE

FIGURE O-1. PDFT DREDGE AND DISPOSAL OPERATIONS



FIGURE O-2. PDFT DREDGE AREA




FIGURE O-3. SAWYER STREET CDF



FIGURE O-4. TEST DREDGE AND SUPPORT EQUIPMENT (OPERATING)



FIGURE O-5. TEST DREDGE AND SUPPORT EQUIPMENT (NOT OPERATING)



FIGURE O-6. TEST DREDGE WITH DISCHARGE AND RETURN WATER LINE



FIGURE O-7. TEST DREDGE



FIGURE O-8. CATERPILLAR 375LC HYDRAULIC EXCAVATOR WITH 4.5 cy HORIZONTAL PROFILING GRAB BUCKET



FIGURE O-9. CRANE MONITORING SYSTEM SCREEN IN ENGINEERS ROOM



FIGURE O-10. HORIZONTAL PROFILING GRAB BUCKET OVER MOONPOOL



FIGURE O-11. HORIZONTAL PROFILING GRAB BUCKET OVER MOONPOOL



FIGURE O-12. MATERIAL HOPPER




FIGURE O-13. BEAN PATENTED SLURRY PROCESSING UNIT



FIGURE O-14. REMOVING ROCK BOX COVER TO CLEAR ROCKS AND DEBRIS FROM SUCTION LINE



FIGURE O-15. DEBRIS IN ROCK BOX



FIGURE O-16. COBBLES, QUAHOGS, AND DEBRIS REMOVED FROM ROCK BOX



FIGURE O-17. SHALLOW DRAFT TUG




FIGURE O-18. WATER QUALITY MONITORING VESSEL WITH TEST DREDGE IN BACKGROUND





FIGURE O-19. PISTON CORE TAKEN DURING DREDGING



GRAY CLAY (CLEAN)

**RESIDUAL SOFT BLACK SILT
(CONTAMINATED)**

FIGURE O-20. PONAR GRAB SAMPLE TAKEN IN PDFT AREA (POST-DREDGE AREA)